BRIGGS&STRATTON

Home Generator Systems

Illustrated Parts List

200 Amp
Automatic Transfer Switch

Model 071021 Manual No. 201705A Rev. B (02/26/2008)

Exploded View - Model 071021



Copyright © 2007 Briggs & Stratton Power Products Group, LLC. All rights reserved. No part of this material may be reproduced or transmitted in any form by any means without the express written permission of Briggs & Stratton Power Products Group, LLC.

Illustrated Parts List - Model 071021

Item	Part #	Description
1	NSP	ASSY, Enclosure
2	NSP	BACK PANEL
3	195668GS	TRANSFER SWITCH, 200A, with Handle
4	*	PPHMS, #10 - 32 x 1/2"
5	*	WASHER, Ext. Tooth, #10
6	*	PPHMS, 1/4-20x 3/4"
7	*	PPHMS, #6- 32 x 3/8"
8	193664GS	INSULATION, Dead Front
9	197279GS	CONTROL, Board
10	201685GS	SPACER
11	196094GS	GROUND LUG
12	*	WASHER, Lock 1/4"
13	192065GS	BREAKER Circuit, 200A
14	*	NUT, 1/4” - 20
15	192696GS	TERMINAL, Neutral
16	B4857GS	FUSE
17	192151GS	FUSE HOLDER
18	197355GS	CLIP, Latching Wire
20	196355GS	DECAL, CT Warning
21	B5106GS	DECAL, Connection, Utility
23	196521GS	DECAL, 200A, ATS
25	205395GS	DECAL, Warning Shock
26	190984GS	DECAL, Fuse
27	B4986GS	DECAL, Ground
28	192597GS	DECAL, Sensing, Utility
29	193450GS	DECAL, Breaker, Circuit
30	*	PPHMS, #10 - 32 x 3/4"
31	192150GS	SPACER
32	197198GS	DECAL, Wire Circuits
33	192879GS	INSULATION, Circuit Breaker
34	197294GS	DECAL, Contacts Rating
35	192881GS	BUS BAR
36	*	LOCKWASHER, #10
37	*	PPHMS, #10 - 32 x 1/4"
38	193159GS	DECAL, Reinstall Barrier

Items Not Illustrated

	195728GS	CURRENT TRANSFORMER

* - Items without part numbers are common fasteners and are available at local hardware stores.